

### ALCOHOL CAT FOOD CAN STOVE

- WASHED 3oz CAT FOOD CAN
- WORK GLOVES
- 1 HOLE PUNCH
- FLATHEAD SCREW-DRIVER
- ALUMINUM FOIL
- SAFETY GLASSES





FLATTEN THE SHARP  
EDGE THAT WAS LEFT  
BY THE LID W/  
FLAT HEAD  
SCREWDRIVER







JUST BELOW LIP OF  
CAN, MAKE ONE  
COMPLETE ROW OF  
HOLE PUNCHES,  
ABOUT  $\frac{1}{8}$ " APART





- BELOW FIRST LAYER OF  
HOLE PUNCHES, MAKE  
ANOTHER ROW OF HOLES  
\* MIDDLE OF BOTTOM  
HOLES SHOULD BE  
DIRECTLY UNDERNEATH  
 $\frac{1}{8}$ " GAPS BETWEEN  
UPPER HOLES




READY  
TO  
TRY IT?






HOT COCOA  
2 HOT COCOA PACKETS  
12 OZ WATER  
METAL CUP OR POT  
PIECE OF ALUMINUM  
FOIL FOR UNDERNEATH  
DENATURED  
ALCOHOL  
MATCHES/LIGHTER  
SPOON FOR STIRRING  
POT HOLDER





PUT FOLDED UP  
PIECE OF  
ALUMINUM FOIL  
UNDER STOVE





POUR SMALL  
AMOUNT OF  
DENATURED ALCOHOL  
INTO STOVE  
(TRY STARTING  
WITH  $\frac{1}{2}$  - 1 OZ)





CAREFULLY  
LIGHT ALCOHOL  
WITH A MATCH  
\*USE CAUTION AS  
ALCOHOL BURNS  
CLEAR



WAIT 20-30 SECONDS  
FOR THE FUEL TO  
WARM UP, THEN  
PUT METAL POT OR  
CUP (FILLED WITH  
12 OZ WATER) ONTO  
STOVE





IF WINDY, MAKE  
WINDSCREEN OUT  
OF FOLDED UP  
ALUMINUM FOIL AND  
CAREFULLY PLACE  
AROUND STOVE





IF FUEL RUNS  
OUT, ADD A LITTLE  
MORE DENATURED  
ALCOHOL + LIGHT  
AGAIN





WAIT FOR WATER  
TO BOIL (SHOULD  
TAKE 5-7 MINUTES)  
AND REMOVE POT  
FROM STOVE  
USING POT HOLDER/  
GLOVES





STIR IN 2 PACKS  
OF HOT COCOA  
AND  
ENJOY!  
#PLAY ROANOKE